

Event Type: Fire Ignites Under UTV Floorboard

Date: May 21, 2017

Location: Moose Creek Prescribed Fire, Alaska This Has Happened Before!

> See Page 2 for Details.

NARRATIVE

While using a 2013 Polaris 6x6 UTV on a prescribed fire, an accumulation of fine fuels located in an enclosed compartment under the UTV's floorboard and above the skid plate ignited.

This fire melted a four-inch hole in the skid plate and floorboard and caused extensive damage to wiring and the gear selector cable. (See top photo on right.)

LESSONS

- Periodically clean out under floorboards of UTVs.
- Standard operating procedures include hosing down the under carriage of UTVs after use.
- The compartment under the floorboards is not obvious and is not easily cleaned by daily washing.
- ✓ To thoroughly clean this compartment, the panel on the floorboard needs to be opened and cleaned out. (Need to remove the eight T-27 torx screws.)
- A contributing factor to this ignition of the fine fuels was the fact that they were operating in a dry site. Typically, spring burning in Alaska involves driving through puddles. The combination of accumulated fuels and these dry conditions made the fine fuels available to burn.
- Typically, UTVs function without damage driving through low-intensity flames.
- All UTVs on this unit will have an inspected and maintained fire extinguisher mounted on them.

This RLS was submitted by: Module/Crew Overhead


Do you have a Rapid Lesson to share? Click this button:

> Share Your Lessons



<u>TOP PHOTO</u> – Shows the damage to the wiring and gear selector cable caused by the fire that occurred under the UTV's floorboard.

<u>BOTTOM PHOTO</u> – Shows some fine fuel accumulation under a companion UTV's floorboard.



Two Previous Cases of Vegetation Accumulating Beneath Floor Panel/Skid Plate on UTVs

Rapid Lesson Sharing

Event Type: Removing Combustible Debris Beneath Floor Plates on Polaris Rangers Location: Wichita Mountain National Wildlife Refuge Fire Shop – Oklahoma Narrative

weeks ago, our fire staff decided to add a small work light on the rear of our 2011 6x6 P es region of the same tool of the same two regions of the feed of the solution of the same so ure, they fou ull of cure



debris was taken, it was The material, packed in tightly, completely filled the

Although it desn't appear that there is a potential ignition source under the floor board, given how these machines are operated, it would be very easy for an external ignition source to light the accumulated material—causing a fire that would be extremely hard to access and put out.

While the floor panel is plastic—and consequently flammable—the underside of the compartment is a metal side plate that has a few factory holes. The location of this compartment push it close to the fuel tank, located on the passenger side, also constructed of plastic. Should accumulated vegetation catch fire in there, it places a substantial ignition source close to the gas tank.

lessons

compartment

Our recommendation is to make removing the floor plats part of your vehicle inspections—and doing so at a minimum of none a month. Realisticative, any time the vehicle has been driven in taller grass [1 to 2 feed)—that sould be forced through the holes into the under-floor compartment—the access panel should be removed to Jean out any material that has accumulated. This will

https://www.wildfirelessons.net/viewdocument/polarisflammable-debris-2014

When they removed the plastic floor panel from their 6x6 Polaris Ranger UTV they found that the entire compartment underneath the floor panel was completely full of cured grass, sticks, and other dead vegetation.

Described as looking "like a hay bale," the materialpacked in tightly—completely filled the compartment.

Given how these machines are operated, it would be very easy for an external ignition source to light the accumulated material—causing a fire that would be extremely hard to access and put out.

http://safenet.nifc.gov/view_safenet.cfm?id=36142&_ncforminfo=9tJAt0U5d_0NmR_i53ZA2fbyB-YYO7SxROHDJ50h7GJw9D3Vym6JCCea1CDQbBlw36rySMZvnr16lugmRYDIrzBGk9bq3yqT

NATIONAL SAFENET HOR		PARLEARENCES Protocols Form Field Definitions FAQ Contact NIFC Home
SAFENET About - Presentation - Annual Summary	SAFENET	SAFENET Wildland Fire Safety & Health Reporting Network
Forms Paper Form Paper Form Field Card Memo Fi	SAFERE LEVENT INFORMATION SAFENET ID: Event Start Date: Event Start Date: Event Start Date: Incident Name: Fire Number: State: Jurisdiction: Local Unit: Incident Activity: Stage of Incident: Position Title: Task: Management Level: Resources Involved: Contributing Factors	Cteate Agency Corrective Action 2016/070-0001 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 07/04/2016 1730 New Mexico BLM Pecces District Wildland Line Initial Attack Senioric FireRighter Supression 5 UTV
	Contributing Factors: Human Factors:	Equipment, Environmental

Possible vegetation lodged between skid plate and underbody ignited, burning a hole through floorboard on this 2009 Polaris Ranger 6X6 UTV.

Firefighter noticed flames protruding through the floorboard. A shovel with sand and the UTV fire extinguisher were used to suppress the flames.