

Event Type: Drone Intrusion

Date: May 20, 2017

Location: Pinal Fire, Tonto National Forest Arizona

This drone intrusion seriously compromised active helicopter operations at the Helibase and prevented an incident helicopter from returning from its mission until the intrusion was cleared.

NARRATIVE

On May 20 at approximately 1805, an Unmanned Aerial Systems (UAS)—or drone—was spotted 60 yards from the Pinal Fire Helibase at approximately 50 feet above ground level.



[This is not the drone that was involved in this incident.]

The UAS was flying in the designated flight path of this incident's helicopters where they were making their descents to land at the Pinal Fire Helibase, located within the city limits of Globe, Arizona. The UAS was white in color and approximately two feet in diameter.

Helitack personnel were able to track the UAS (drone) while it was in flight. They were proactive in tracking the UAS and following its flight path. They observed the aircraft descend and land at a nearby residence in the vicinity of the Pinal Fire Incident Command Post. Upon seeing the UAS, Helibase personnel contacted Helicopter OTA, an incident helicopter that was flying a mission over the fire, to inform the pilot of the UAS intrusion into the Temporary Flight Restriction (TFR) and the hazard associated with the UAS being in the area.

The helicopter was asked to not come back to the Helibase until fire personnel were sure that the UAS was clear of the area. The Helibase Manager immediately called the Air

Operations Branch Director (AOBD) to inform him of the UAS intrusion. The AOBD, in turn, contacted incident Law Enforcement—who responded immediately to the Helibase.

Helitack personnel were able to track the UAS while it was in flight. They were proactive in tracking the UAS and following its flight path. They observed the aircraft descend and land at a nearby residence in the vicinity of the Pinal Fire Incident Command Post.

UAS (Drone) Operator Located and Cited

The LEO arrived at the Helibase. He was informed of the location where the UAS descended and landed. The LEO had enough information to go make contact with the UAS operator and was able to confiscate the UAS and cite the individual.

This UAS intrusion within the TFR posed a serious safety concern for incident pilots and fire personnel involved in helicopter aviation missions on the Pinal Fire. The UAS intrusion impeded the operations of the Helibase and—should a collision occur—posed a serious hazard.

The UAS intrusion within the TFR posed a serious safety concern for incident pilots and fire personnel involved in helicopter aviation missions on the Pinal Fire. Quick and decisive action by the Pinal Fire Helibase Manager, incident Helibase Crewmembers, and local Law Enforcement personnel brought this intrusion incident to a quick and decisive resolution.

LESSONS

- Establish appropriate TFRs early in the incident and ensure that the incident Helibase is included in the polygon.
- All fire personnel should stay alert to the possibility of UAS intrusions, particularly when operations are in or near an urban setting.
- If a UAS is sighted within a fire's theater of operations, ensure that the intrusion is communicated to all incident personnel.
- If a UAS intrusion should occur, ensure that incident personnel are diligent and persistent in documenting information relative to the intrusion, including: UAS description, direction of flight, and—if possible—determining the originating location of the UAS for LEO follow-up.
- Provide UAS cautionary messaging as part of the incident narrative summary in INCIWEB.

SAFECOM

A SAFECOM was also filed on this incident:

Tracking # 17-0276

This RLS was submitted by:

Natalie Bench, Pinal Fire Helibase Manager Donald Muise, Pinal Fire SOF2 Do you have a Rapid Lesson to share?

Share Your Lessons