

Forest Service 159 Lawrence Street Quincy, CA 95971-6025 (530) 283-2050 TTY/TDD: (530) 234-7984 http://www.fs.fed.us/r5/plumas

File Code: 5100/6300 Route To:

**United States** 

Agriculture

**Department** of

Date: July 14, 2017

Subject: Crescent Fire Burn Injury; 72-hour Briefing

To: Peter Tolosano and Jeffrey Bradshaw

THE FOLLOWING INFORMATION IS PRELIMINARY AND SUBJECT TO CHANGE

Location: Plumas National Forest, California

Date of occurrence: July 1, 2017

Time of occurrence: Approximately 1159 hours

Mission: Fire Suppression

Activity: Engine Operation, Pumping Hoselay

Number injured: One hospitalized

Number of fatalities: None

**Property damage:** One section of hose, (unknown Engine damage)

**Narrative:** While pumping a hoselay on the right flank of the Crescent Fire (approximately 40-50% slope) the MDF Engine Operator received notification that no water was reaching the uppermost part of the hoselay. The Engine Operator received second degree burns to 17 percent of his/her body when a hose blew at the pump panel (under approximately 295 psi) with above average (for the operation) water temperature.

The injured Engine Operator received immediate aid from nearby crewmembers and was later transported to UC Davis Burn Center in Sacramento.

The Engine is being transported to San Dimas T&D center for further analysis.

A Facilitated Learning Analysis (FLA) Team has been assigned to the incident to determine what can be learned from this incident.

DANIEL A. LOVATO Forest Supervisor

cc: Randy Moore, Regional Forester, Jeanne Wade Evans, Deputy Regional Forester, Scott Lucas Forest Fire Chief Plumas,

